



Slat Shield Plus is a slag/dross preventative that can be applied to new or cleaned slats. Slat Shield can be applied to copper as well as steel laser cutting beds. The Slat Shield Plus should be applied weekly or every time a laser bed is cleaned. It doesn't have to be diluted but it can have up to 25% water to 75% solution.

#### Notes

- Increased machine uptime
- Reduction in slag/dross buildup on slat
- Reduce splatter on backside of cut parts
- Non flammable
- Non aerosol

1.866.995.9910

**FMS** | Fabricating  
Machinery  
Solutions Inc. ♦

[www.fmscanada.ca](http://www.fmscanada.ca)